

Website: LegacyLLC.com


General Inquiries: contact@legacyllc.com

Orders: orders@legacyllc.com


**Main Office:** 415 Concord Avenue Bronx, NY 10455 **Phone:** (718)292-5333 **Fax:** (888)383-3330

## Single Flood Shield for Standard Windows






## #5028 MOUNTED TO INSIDE OF FRAME



## #5128 MOUNTED TO OUTSIDE OF FRAME






Website: DoorFloodBarrier.com

General Inquiries: contact@legacyllc.com

Orders: orders@legacyllc.com

Main Office: 415 Concord Avenue Bronx, NY 10455

**Phone:** (718) 292-5333 **Fax:** (888) 383-3330



## **Product Specifications**

**PANEL:** 5052 type Marine-grade Aluminum Alloy

**INSIDE MOUNTED FRAMES:**  $1-1/4" \times 29/32" \times 1/8"$  aluminum extrusion 6062 alloy T5-T6, with 10-32 stainless steel allen head tightening. Black anodized channels are also available if specified.

**OUTSIDE MOUNTED FRAMES:** 1-1/4" x 29/32" x 1/8" aluminum extrusion 6062 alloy T5-T6, with 10-32 stainless steel allen head tightening. Black anodized channels are also available if specified.

FLOOR SURFACE: We recommend our 319 threshold (1/4" x 2" beveled aluminum plate).

**SEALS:** Neoprene lines the bottom of the shield. Sponge Rubber lines the channels. Our seals are composed of high-density rubber extrusions for increased strength with a low hardness that provides superior compression.

HARDWARE: #10 x 1-1/2" FHPH with plastic expansion tube anchors. Snap covers for

safety provided for the top of the channels and for the mounting holes.

**INSTALLATION:** Can be installed on hollow metal, aluminum or wood frames; and on concrete, brick or metal surfaces.

Project:	Submitted By :
Date:	Notes:
Company Name :	